


FIG.1







VD IId×Rp T=Rp×C POTENTIAL AT POINT A POINT A POTENTIAL AT POINT B Vb T=Rsw1×Cs




FIG.6









FIG.7




















10/21






12/21



**FIG.17** 



13/21

FIG.18 (VOLTAGE DRIVE)





FIG.19 (CURRENT DRIVE)



14/21

FIG.20 (WHEN TURNING OFF LASER)




FIG.21
(WHEN APC)

423

424

421

422

432

433

434

N2


411


412


416

417


416













19/21

**FIG.26** 












FIG.29



**FIG.30** 



21/21




FIG.33

105

104

BACK LIGHT

102

LIGHT OUTPUT